

Fig. 2




Fig. 3




Fig. 4




Fig. 5

6/23




Fig. 6



103




Fig. 8







Fig. 9






FIG. 11 is a schematic diagram of a mechanical assembly, showing a base 106, a lever 103, and various components including 104, 105, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, and 130. The diagram illustrates the mechanical linkage and components of the assembly.

Fig. 11









Fig. 13








Fig. 15






Fig. 16






Fig. 17




Fig. 18




Fig. 19




Fig. 20




Fig. 21






Fig. 22

